



Troubleshooting Guide

Handpiece Hot – Probable Causes

Handpiece Hot

Pinion Gear Tight in Handpiece Bearing

Blade Tight in Blade Housing (large tools only) Handpiece Bearing Not Installed Correctly (no clearance between face of pinion gear and blade housing) Causing Mechanical Bind.

Clean Corrosion from the Handpiece Bearing and Lubricate. Adjust Blade Housing (large tools only).

Reinstall Bearing
Correctly. With Handpiece
Removed from the
Driveline or Flex Shaft, the
Blade Should Rotate
Freely by Hand.



bettcher.com/support